NEVERSE

700k OCT 20 A 5: 43

Revised 10/04

ACTION

CORRES. CONTROL INCOMING LTR NO.

OUT DUE DATE

INCOMING LTR NO.

TO CORRESPONDENCE

CONTROL

Department of Energy

ROCKY FLATS PROJECT OFFICE 10808 HIGHWAY 93, UNIT A GOLDEN, COLORADO 80403-8200

OCT 1 2 2004

04-DOE-00762

		. 1
DIST.	LTR	ENC
BERARDINI, J.H.	X	X
BOGNAR, E.S.	X	Y
BROOKS, L.	IΥ	×
BUTLER, L.	İΧ	χ-
CARPENTER, M.	ΪX	Y
CIUCCI, J.A.	\vdash	
CROCKETT, G. A.	1	
DECK, C. A.	X	X
DEGENHART, K. R.	X	x
DEL VECCHIO, D.	TX	X
DIETER, T. J.		
FERRERA, D. W.	IX	X
GIACOMINI, J. J.		
LINDSAY, D. C.	IX	X
LONG, J. W.		·
LYLE, J. L.		$\overline{}$
MARTINEZ, L. A.	X	X.
NAGEL, R. E.	X	X
NESTA, S.	IX	X
NORTH, K.	X	X
SHELTON, D. C.	TX	\mathbf{x}^{-}
SPEARS, M. S.	\mathbf{X}	X
TUOR, N. R.	IX.	X
WIEMELT, K.	A	12
WILLIAMS, J. L.		
ZAHM, C.	I X	X
FOSS D	<u>LX</u>	<u>X</u>
•		
Gibbs F	IX_	X.
	<u> </u>	L
	1	Щ.
	ـــــ	<u></u>
	_	L_
	L	<u> </u>
	1	L_
	!	
	-	<u> </u>
	1	

COR. CONTROL	IX	X
ADMIN. RECORD	X	X
PATS/130	Γ	

Reviewed for Addressee Corres, Control RFP

10/20/04	a c
Dale	Ву

Ref. Ltr. # <u>04RF00980</u>

5400 · 1

Mr. Steven H. Gunderson Rocky Flats Cleanup Agreement Project Coordinator Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Dear Mr. Gunderson:

In accordance with the Rocky Flats Cleanup Agreement (RFCA) Standard Operating Protocol (RSOP) for Facility Disposition, this letter and its enclosures is notification for RSOP implementation of Building 451. This notification will utilize a combined RSOP strategy for demolition:

- > The portions of the building that meet unrestricted release will be demolished in accordance with the RSOP for Facility Disposition.
- > The portions of the building that do not meet unrestricted release will be removed in accordance with the RSOP for Component Removal, Size Reduction, and Decontamination Activities, Section 3.8. The six point analysis will be addressed by contact record as it is combined with Building 447.
- > The slab will remain in place and protected until the entire building has been demolished; the slab will be removed in accordance the RSOP for Environmental Remediation.

The Reconnaissance Level Characterization Report for Building 451 was submitted to the Colorado Department of Public Health and Environment (CDPHE). The Pre-Demolition Survey Report was submitted to CDPHE on November 21, 2002. Building 451 has been determined to be a Type 2 facility due to radiological contamination in excess of the uranium Derived Concentration Guide and widespread beryllium (Be) contamination in the first filter stage. A fixative has been applied to the Be remaining in the building to reduce the Be potential for release during demolition. The Utility Room and south-side of the second filter stage of Building 451 meet free release criteria. Fixed radiological contamination remains in the demister, first filter stage, and north side of the second filter stage. These portions of the building will undergo demolition with residual radiological contamination. Enclosed is a description of work and schedule

This notification dealing with this work will be conducted by Kaiser-Hill Company, LLC (K-H). The requirements, methods, controls, and processes outlined in the RSOP will be followed. This work will be conducted in accordance with the work control documentation



ADMIN RECORD

B444-A-000089

prepared by K-H and its subcontractor. The exact methods and process and progress of the activities will be communicated through the consultative process. A schedule for this work is enclosed.

Questions may be directed to Gary P. Morgan at (303) 966-6003.

Joseph A. Legare, Director RFPO Project Management

Enclosure

cc w/o Encl.:

F. Gibbs, K-H RISS

S. Nesta, K-H RISS D&D

D. Foss, K-H RISS D&D

M. Aguilar, USEPA

cc w/Encl.:

F. Lockhart, OOM, RFPO

G. Morgan, HQCPM, RFPO

Administrative Record

RECEIVED

CONTROL



04-RF-00980

SEP 2 3 2004

Gary Morgan, Functional Lead Cadre Project Management Division DOE, RFPO

RSOP FOR FACILITY DISPOSITION NOTIFICATION LETTER FOR BUILDING 451 FEG-030-04

Attached is a draft transmittal letter to the Colorado Department of Public Health and Environment for the RSOP notification for Building 451 facility disposition. The draft transmittal letter has been prepared from DOE building point of contact to CDPHE building point of contact; however, it could also be addressed from DOE RFCA coordinator to CDPHE RFCA coordinator.

Please contact Steve Nesta X6386 with questions or concerns.

Frank E. Gibbs

Deputy Project Manager

Remediation, Industrial D&D, and Site Services

SMN:pvt

Attachment:

As Stated

Orig. and 1 cc - Gary Morgan

CC:

Joe Legare

5400

David Kruchek Colorado Department of Health and Environment 4300 Cherry Creek Drive South Denver, CO 80222-1530

RSOP FOR FACILITY DISPOSITION NOTIFICATION LETTER FOR BUILDING 451

Mr. Kruchek:

In accordance with the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Facility Disposition, this letter and its attachments is notification for RSOP implementation. This notification is for all activities required to demolish and disposition Building **451**.

The Reconnaissance Level Characterization Report for Building **451** was submitted to CDPHE, and received official concurrence on **11/21/02**. Building **451** has been determined to be a Type **2** facility due to radiological contamination in excess of the uranium DCGL_W and widespread Be contamination in the 1st filter stage. A fixative has been applied to the Be remaining in the building to reduce the Be-potential for release during demolition. The Utility Room and south-side of the 2nd filter stage of Building **451** meet free release criteria. Fixed radiological contamination remains in the demister, 1st filter stage, and north side of the 2nd filter stage. These portions of the building will undergo demolition with residual radiological contamination.

This work will be conducted by Kaiser-Hill Company, L.L.C (K-H). The requirements, methods, controls, and processes outlined in the RSOP will be followed. This work will be conducted in accordance with the work control documentation prepared by K-H and its subcontractor. The exact methods and process and progress of the activities will be communicated to DOE/LRA through the consultative process. A schedule for this work is attached.

As indicated in the RSOP, the LRA has 14 days to review the RSOP notification letter and provide feedback, including a definitive reason for not proceeding with the project. If no feedback is received within 14 days, the project will proceed as planned.

If you have any questions regarding this, please contact me at (303) 966-6003.

Gary Morgan U.S. Department of Energy

DESCRIPTION OF PLANNED ACTIVITIES

Facility Description and Scope of Demolition

Building 451 is a 2780-sq. ft. two-stage HEPA filter plenum located south of Building 447. The filter plenum was constructed in 1983 and provided ventilation to Buildings 447 and 448. Building 451 is a single-story steel-framed building constructed on a concrete slab. The walls and roof are constructed of corrugated steel, with several marine-type airtight access doors.

Building 451 was serviced by the following utilities: water and electric. Fire suppression is provided by overhead sprinkler system.

Demolition of the structure will be executed by heavy equipment. The demolition equipment will begin on the south side of the building and proceed northward. Efforts will be made, if possible, to ensure that debris falls within the building footprint. The demolition will commence with the utility room and south-side of the 2nd filter stage starting from the southwest side of Building 451. Debris from this portion of the demolition will be managed at a non-routine sanitary waste and disposed at an RFETS approved landfill (Front Range or BFI – Commerce City). The north side of the 2nd filter stage, the 1st filter stage, and demister portions of Building 451 will undergo demolition with residual radiological contamination. Debris from this portion of the demolition will be managed as low level waste and disposed at Enviorcare of Utah. The Building 451 slab did not come into direct contact with the building's interior as Building 451 had a separate metal floor. However, post demolition beryllium and radiological surveys will be performed and used to determine an appropriate disposal path for the slab. If survey results are acceptable, the Building 451 slab will remain in place, as it is four (4) feet below final grade.

Pre-Demolition Survey Report (PDSR)

During the RLC, radiological survey results indicated that radiological Contamination in excess of the-uranium DCGL_W was present throughout the demister and 1st and 2nd filter stages of building 451. Also, surveys identified beryllium (Be) contamination throughout the facility. The Be and uranium contaminated areas of the utilities room and 2nd filter stage (south-side) have been decontaminated and/or removed under implementation of the Facility Component Removal, Size Reduction, and DecontaminationActivities RSOP. The demister, 1st filter stage, and north side of the 2nd filter stage will undergo demolition with residual radiological contamination. A Pre-Demolition Survey report (PDSR) has been prepared that verifies the effectiveness of the decontamination for the utilities room and south side of the 2nd filter stage of building 451. Also, the PDSR establishes that no removable beryllium or radiological contamination is present in the demister, 1st filter stage, and north side of the 2nd filter stage of the facility. The PDSR establishes the building as being ready for demolition and is being submitted concurrently with this RSOP notification.

<u>Project-specific Administrative</u> Record File Index Attached

Deviations or Exceptions to the to the RSOP None

Level One Schedule for Project Implementation Attached

Point of Contact

The principle point of contact for this project is Karl Shuler, (303) 966-3423.

Activity	- Activity	%	Orig	Rem C	Current	Current		FY04		FY05		
ID.	Description	Comp		Dur	Earty	Early	·	P		ост	NOV	
4.17 December	Environmental Environment				Start	Flaish	<u> </u>	35.1113	7.,11 111.	138125	1118125	
	B447 Apply Fixatives	100	3	0	13SEP04A	20SEP04A						
1EDD447A21	8447 Utility Disconnects	100	2	0	16SEP04A	20SEP04A	1	-				
EDD447A1	B447 Demo Permit Approved	0	1	1	23SEP04°	23SEP04		•				
EDD447A11	B447 Demo Mobilization	0	1	1	27SEP04	27SEP04]		,			
IEDD447A41	B447 Demolish Building	O	5	5	28SEP04	04OCT04						
IED0447A51	B447 Loadout Debris	O	8	8	05OCT04	15OCT04				-		
	B447 Demobilize Site	0	2	2	18OCT04	19OCT04						
i 51 - Filler Plar	num Bing (5 of 447) for B447											
1EDD451A1	B451Demo Permit Approved	100	1	0	16SEP04A	20SEP04A] ,	7	1			
EDD451A21	B451Utility Disconnects	100	2	0	16SEP04A	20SEP04A		7				
EDD451A31	B451Apply Be Fixatives	100	. 3	0	17SEP04A	20SEP04A		•				
EDD451A11	B451Demo Mobilization	0	1	1	27SEP04*	27SEP04			,			
EDD451A41	B451Demolish "cold" portion Filter Plenum	G	2	2	28SEP04	29SEP04		1	7			
EDD451A71	B451 Loadout "cold" portion Filter Plenum	0	2	2	30SEP04	01OCT04						
EDD451A81	B451 Demo "contaminated" portion Fitter Plenum	0	3	3	04OCT04	06OCT04						
EDD451A51	8451 Loadout "contaminated" portion Fitr. Plenum	0	3	3	07OCT04	12OCT04		<u> </u>				
IEDD451A61	B451Demobilize Site	0	2	2	13OCT04	14OCT04				•		
Start Date	01FEB99					=	tiofi				F-4-D	
inish Date	03APR06	Date Revision ineckapproved			Earry Bar							
lata Date	20SEP04				Progress Bar							
un Date	20SEP04 13:31				September 20	004					- · ·	
											•	

FISR_AR_GENERAL_QUERY.RD

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE CERCLA ADMINISTRATIVE RECORD - GENERAL QUERY

Page: 1 of 3 Report Date: 22-SEP-04

Doc. No. / Date	Routine Int	There are 12 records in this set and a total of ernal Code	516 pages. Title / Subject
B444 A 000001 11/01/1998 Aut 146 Pages JOI PUBLIC MA		· · · · · · · · · · · · · · · · · · ·	444 Cluster Removal Project, Project Execution Plan (PEP) Initial Issue: Hazards Reduction, Revision 0 effective December 1, 1998. The Cluster Closure Project includes complete demolition and removal of the remaining 13 facilities in the cluster. The purpose of the B444 Cluster Removal Project is to support the site mission of safely closing all facilities and operable units in a short amount of time and to reduce landlord costs. Fixed Price with Economic Price Adjustment (FPEPA)
	YES, ROUTINE WJ hor(s) CANDREW, WILLIAM J	Recipient(s)	Rocky Mountain Remediation Services, L.L.C. (RMRS) transmits the Plan for Safe Shutdown of Building 444 Cluster dated February 1997, Revision 0, to Kaiser-Hill Company, L.L.C. (K-H).
B444 A 000007 03/05/2002 Aut	YES, ROUTINE NA hor(s) EIBOTH, C. J.	Recipient(s) HINDMAN, JAMES	Purpose of Contact: Building 444 Complex Scoping Meeting Minutes. The complex includes Buildings 427, 427A, 444, S444, 445, 447, 448, 449, 449A, 449C, S449, 450, 451, 453, 454, 455, and 457. Kaiser-Hill Company, L.L.C. (K-H) projected that Buildings 444, 447, 448, 450, 451 and 455 will be Type 2 facilities and the remainder being Type 1. The Colorado Department of Public Health and Environment (CDPHE) projects that, Building 444 and 447 might be a Type 3.
10/09/2002 Aut	YES, ROUTINE 02- hor(s) GARE, JOSEPHA.	DOE-01524; 00692-RF-02 Recipient(s) GUNDERSON, STEVE	Forwards the attached [000014] Reconnaissance Level Characterization Report (RLCR) for Buildings 444, 445, 447, 448,450,451 and 455. These buildings are determined Type 2 facilities due to the moderate to mild depleted Uranium (U) and Beryllium (Be) contamination in accordance with the Decommissioning Program Plan (DPP) and this determination is submitted for Lead Regulatory Agency (LRA) concurrence.

FISR_AR_GENERAL_QUERY.RD

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE CERCLA ADMINISTRATIVE RECORD - GENERAL QUERY

Page: 2 of 3 Report Date: 22-SEP-04

There are 12 records in this set and a total Doc. No. / Date Routine Internal Code	of 516 pages. Title / Subject
B444 A 000012 YES, ROUTINE 00804-RF-02 1/14/2002 Author(s) Recipient(s) 2 Pages GUNDERSON, STEVE LEGARE, JOSEPH A. PUBLIC	The Colorado Department of Public Health and Environment (CDPHE) has reviewed the Reconnaissance Level Characterization Report (RLCR) for the Building 444 Cluster Closure Project. Revision 0 dated September 5, 2002. In accordance with the Section 3.3.4 of the Decommissioning Program Plan (DPP), the Division concurs with the determination that Buildings 445, 448, 450, 451 and 455 are Type 2 facilities. They agree that most of Buildings 444 and 447 are Type 2, however their concurrence is subject to Divisor approval of work packages prior to conducting work and the following items are listed along with the CDPHE comments on the RLCR.
B444 A 000013 YES, ROUTINE 02-RF-01958; DWF-080-02 09/12/2002 Author(s) Recipient(s) 1 Pages FERRERA, DENNIS W. TOWER, STEVE PUBLIC	Submits the attached [000014] Reconnaissance Level Characterization Report (RLCR) 444 Cluster Closure Project, Buildings 444, 445, 447, 448, 450, 451 & 455, Revision 0 dated September 5, 2002 for review and approval.
B444 A 000014 YES, ROUTINE Ref: 02-RF-01958; DWF-080-02 09/05/2002 Author(s) Recipient(s) 328 Pages NOT INDICATED DISTRIBUTION PUBLIC PUBLIC	Reconnaissance Level Characterization Report (RLCR) 444 Cluster Closure Project, Buildings 444, 445, 447, 448, 450, 451, and 455, Revision 0 September 5, 2002 [Type 2]- This report characterizes the physical, chemical and radiological hazards associated with these facilities, summarizes the characterization activities, defines the Data Quality Objectives (DQOs) developed for this characterization, and presents the data quality assessment, verification and validation of results.
B444 A 000032 YES, ROUTINE 03-RF-00056; FEG-002-03 01/14/2003 Author(s) Recipient(s) 7 Pages GIBBS, FRANK E. TOWER, STEVE PUBLIC	Encloses a draft transmittal letter to the Colorado Department of Public Health and Environment (CDPHE) for the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) Notification for Building 444 Cluster Closure Project, Buildings 444, 445, 447, 448, 450, 451, and 455 Component Removal, Size Reduction and Decontamination.

-21-2

FISR_AR_GENERAL_QUERY.RD

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE CERCLA ADMINISTRATIVE RECORD - GENERAL QUERY

Page: 3 of 3 Report Date: 22-SEP-04

	516 pages.
Doc. No. / Date Routine Internal Code B444 A 000035 YES, ROUTINE 03-DOE-00066; 00062-RF-03 01/30/2003 Author(s) Recipient(s) 10 Pages DISALVO, RICHARD GUNDERSON, STEVE PUBLIC B444 ≜ 000044 YES, ROUTINE 00261-RF-03; Ref: 03-DOE-00066; 00062-RF-03 03/06/2003 Author(s) Recipient(s) 1 Pages GUNDERSON, STEVE DISALVO, RICHARD	Forwards the enclosed Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Component Removal Notification Form for Building 444 Cluster, which includes 444, 445, 447, 448, 450, 451 and 455. This letter and its enclosures are notification for RSOP implementation. The Colorado Department of Public Health and Environment (CDPHE) agrees with utilization of the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Facility Component Removal, Size Reduction, and Decontamination
PUBLIC B444 A INFO YES, ROUTINE N/A	Activities for Buildings 444, 445, 448, 450, 451 and 455. Information Only Entry: The Building 444 Cluster Closure Project involves the following buildings: 427, 444, 445, 447, 448, 449, 450, 451, 453, 454, 455, and 457. Buildings 427A and T444A were originally part of the Cluster but were previously removed. Part of all of the following Individual Hazardous Substance Sites IHSS are within the area of this Cluster: 116.1, 121, 136.2, 157.2, 189, 208, 116.2, 136.1, 147.1, 182.0, and 207. UBC-444, "Under Building Contamination Bldg. 444' is also within the area of the Cluster; there are 11 Resource Conservation Recovery Act (RCRA) Units.
IA A INF○ YFS, ROUTINE Ref: B444-A-000014; 02-RF-01958; DWF-080-02 09/05/2002 Author(s) Recipient(s) 0 Pages RISS, D&D GROUP DISTRIBUTION PUBLIC PUBLIC	Information Only Entry: RISS / 444 Cluster Facility Characterization Historical Site Assessment (HSA) Report, January 1, 2002 - Building 451 is a two stage HEPA Filter Plenum located south of Building 447. The filter plenum was constructed in 1983 and provides ventilation to Buildings 447 and 448.